All issues were reported to Staffordshire County Council via the Report It function www.staffordshire.gov.uk/reportit

Salting and gritting map

https://www.staffordshire.gov.uk/transport/staffshighways/winterdriving/salting/Saltingroutes.aspx

Reported issue –	Date	Highways	Follow up	Comments
location and	reported	reference	date	Comments
requested action	reported	number	uale	
Pot hole and flattened	21.10.2017	4094161	24.10.2017	Sent photo of large pot hole and flattened black
black/white posts on	21110.2011	1001101	01.03.2018	and white posts.
corner of		4201024		and write posts.
		1201021	23.05.2018	Maria Maria
A522/Waterloo Farm,			01.11.2018	
Pigeonhay Lane,			20.02.2019	
Beamhurst, ST14 5dy				And the second s
			10.06.2020	
			24.07.2020	Minico
			24.07.2020	MINISHIE .
				01.11.2018 – clerk called highways for an update,
			19.01.2022	as noticed this still not completed – scheduling
				team advised they will highlight it
				1
				20.02.2019 – this is with the scheduling team, as
				a CAT 3
				10.06.2020 Reported again, as main road has
				been repaired, but this is still on their system as
				awaiting scheduling team.
				24.07.2020
				24.07.2020
				This is an anadaka ka arawa an araina daka d
				This is an update to your enquiry dated
				10/06/2020 in relation to PIGEONHAY LANE.
				A highways inspector has now assessed the site
				you reported and arranged a non-urgent works
				instruction.
				10.01.2022 received on annual frame CCC to
				19.01.2022 – received an email from SCC to say
				this issue is on going.
The Cedars	28.01.2020	4186841		Resident reported it and provided photos
Hollington Lane				
STramshall				
OT44 5 A I				
ST14 5AJ				
guttering installed and				
water being				
discharged onto the				
road				
Ioau				
	l			

Flooding on Road, blooked culvert under road. 10,04,2020 4198937 22,04,2020 66,65,2020 66,65,2020 7 7 7 7 7 7 7 7 7	E	10.04.000	4400007		1
Dairy Farm, High Striat Si an update to your enquiry dated 10/04/2020 in relation to HIGH STREET. Hamp post 23 Lamp post 22 Lamp post 23 Lamp post 24 Lamp post 25 Lamp post 26 Lamp post 26 Lamp post 27 Lamp post 27 Lamp post 27 Lamp post 28 Lamp post 29 Lamp post	Flooding on Road,	10.04.2020	4196935	22.04.2020	Map included of area, with arrow to culvert and
Dairy Farm, High Streat, Stramshall, ST14 SAG Lamp post 23 Lamp post 22 New Ref for 20.01.2021 report 4224656 Reopened 20.01.2021 Report 622 Reopened 20.01.2021 Report 722 Reopened 20.01.2021 Report 823 Reopened 20.01.2021 Report 8424656 Reopened 20.01.2021 Report 9424656 Reopened 20.01.2021 Report 9424656 R				06.05.2020	map of drains in the area.
Dairy Farm, High Street, Stramshall, ST14 5AG Lamp post 23 Lamp post 22 New Ref for 20.01.2021 report 4224656 New Ref for 20.01.2021 report 4224656 Recopened 20.01.2021	Toau.			00.03.2020	This is an undate to your enquiry dated
Street, Stramshall, ST14 SAG Lamp post 23 Lamp post 22 New Ref for 20.01.2021 report 4224656 New Ref for 420.01.2021 report 4224656 Neepened 20.01.2021 Trevor Mellor will carry out a site visit today 06.05.2020. This is an update to your enquiry dated 15/05/2020 in relation to STRAMSHALL ROAD. A highways inspector has now assessed the site your report. Other works in the area might still be pending and any unresolved defects will continue to be monitored via our routine safety inspections. Road sign broken ASO – A618 junction Road sign broken ASO – A618 junction 15.07.2020 Road sign broken ASO – A618 junction 15.07.2020 Row Ref for 20.01.2021 A highways officer has now considered your enquiry added the following notes to your report. We have wisted the location provided with your report that we been unable to identify any defects that require are might still be pending and any unresolved. However, if you believe there is still an issue that requires attention may we kindly ask that you contact us again with your reference numbers to that we can verify the location details. Sent to Councillors 22.04.2020 Trevor Mellor will carry out a site visit today 06.05.2020. 15.05.2020 Site visit carried out, Landowner cleared mud from grid at entrance to pipe, Clerk reported again, providing lamp post 23 as a location. 28.05.2020 This is an update to your enquiry dated 15/05/2020 in relation to STRAMSHALL ROAD. Works have taken place in response to your report. Other works in the area might still be pending and any unresolved defects will continue to be monitored via our routine safety inspections. The council of the council of the flood water on the road and reported the issue again. The landowner believes that Lamp post 23 has been installed through the drain and that is why it is going onto the road, not through the drain and that is why it is going onto the road, not through the drain and that is why it is going onto the road, not through the drain and that is why it is going not the road and report	Dairy Farm, High		Reported		
Lamp post 23 Lamp post 22 New Ref for 20.01.2021 report 4224656 New Ref for 20.01.2021 report 4224656 Recopened 20.01.2021 Trevort Melhave welsted the location provided with your report but have been unable to identify any defects that require remedial works at this time. It might be that the problem has now been resolved. However, if you believe there is still an issue that requires attention may we kindly ask that you contact us again with your reference number so that we can verify the location details. Sent to Councillors 22.04.2020 Trevor Mellor will carry out a site visit today 06.05.2020. 15.05.2020 Site visit carried out, Landowner cleared mud from grid at entrance to pipe, Clerk reported again, providing lamp post 23 as a location. 28.05.2020 This is an update to your enquiry dated 15/05/2020 in relation to STRAMSHALL ROAD. A highways inspector has now assessed the site you reported and arranged a non-urgent works instruction – jetting machine 20.07.2020 This is an update to your enquiry dated 15/05/2020 in relation to STRAMSHALL ROAD. Works have taken place in response to your report. Other works in the area might still be pending and any unresolved defects will continue to be monitored via our routine safety inspections. reopened 20.01.2021 Clerk took photos of the flood water on the road and reported the issue again. The landowner believes that Lamp post 21 has been installed through the drain included map of drains for the area with report.	1		again		10/04/2020 III Ciddoil to Tildii 31 KEET.
Lamp post 23 Lamp post 22 15.05.2020 28.05.2020 28.05.2020 28.05.2020 20.01.2021 report delar the full ownever; if you believe there is still a thirty you contact us again with your reference number so that we can verify the location details. Sent to Councillors 22.04.2020 Trevor Mellor will carry out a site visit today 06.05.2020 This is an update to your enquiry dated 15/05/2020 in relation to STRAMSHALL ROAD. A highways inspector has now assessed the site you reported and arranged a non-urgent works instruction — jetting machine 20.07.2020 This is an update to your enquiry dated 15/05/2020 in relation to STRAMSHALL ROAD. Works have taken place in response to your report. Other works in the area might still be pending and any unresolved defects will continue to be monitored via our routine safety inspections. Propend 20.01.2021 Clerk took photos of the flood water on the road and reported the issue again. The landowner resolved in the report of the repor	ST14 5AG				A highways officer has now considered your
Lamp post 23 Lamp post 22 New Ref for 20.01.2021 report 4224656 New Ref for 20.07.2020 closed 4224656 Reopened 20.01.2021 1 report 4224656 Reopened 20.01.2021 Trevor Mellor will carry out a site visit today of 6.05.2020. Trevor Mellor will carry out a site visit today of 6.05.2020. Trevor Mellor will carry out a site visit today of 6.05.2020. Trevor Mellor will carry out a site visit today of 6.05.2020. This is an update to your enquiry dated 15/05/2020 in relation to STRAMSHALL ROAD. A highways inspector has now assessed the site you reported and arranged a non-urgent works instruction – jetting machine 20.07.2020 This is an update to your enquiry dated 15/05/2020 in relation to STRAMSHALL ROAD. Works have taken place in response to your report. Other works in the area might still be pending and any unresolved defects will continue to be monitored via our routine safety inspections. Road sign broken A50 – A518 junction			4198897		enquiry and added the following notes to your
New Ref for 20.01.2021 report New Ref for 20.01.2021 report 4224656 Reopened 20.01.2021 Trevor Mellor will carry out a site visit today 06.05.2020. 15.05.2020 Site visit carried out, Landowner cleared mud from grid at entrance to pipe, Clerk reported again, providing lamp post 23 as a location. 28.05.2020 This is an update to your enquiry dated 15/05/2020 in relation to STRAMSHALL ROAD. A highways inspector has now assessed the site you reported and arranged a non-urgent works instruction – jetting machine 20.07.2020 This is an update to your enquiry dated 15/05/2020 in relation to STRAMSHALL ROAD. Works have taken place in response to your report. Other works in the area might still be pending and any unresolved defects will continue to be monitored via our routine safety inspections. Road sign broken A50 – A518 junction 20.07.2020 Road sign broken A50 – A518 junction 15.07.2020 4205119 17.07.2020 Clir provided photo of broken sign	Lamp post 23			15.05.2020	report: We have visited the location provided
New Ref for 20.01.2021 report 4224656 Reopened 20.01.2021 Trey Mellor will carried out, Landowner cleared mumbers of that we can verify the location details. Sent to Councillors 22.04.2020 Trev Mellor will carried out, Landowner cleared mumbers of the will carried out, Landowner cleared mud from grid at entrance to pipe, Clerk reported again, providing lamp post 23 as a location. 28.05.2020 This is an update to your enquiry dated 15/05/2020 in relation to STRAMSHALL ROAD. A highways inspector has now assessed the site you reported and arranged a non-urgent works instruction – jetting machine 20.07.2020 This is an update to your enquiry dated 15/05/2020 in relation to STRAMSHALL ROAD. Works have taken place in response to your report. Other works in the area might still be pending and any unresolved defects will continue to be monitored via our routine safety inspections. reopened 20.01.2021 Clerk took photos of the flood water on the road and reported the issue again. The landowner believes that Lamp post 23 has no intalled through the drain and that is why it is going onto the road, not through the drain. Included map of drains for the area with report.	Lamp post 22			28.05.2020	
resolved. However, if you believe there is still a issue that requires attention may kindly ask that you contact us again with your reference number so that we can verify the location details. Reopened 20.01.2021 Reopened 20.01.2021 Reopened 20.01.2021 Trevor Mellor will carry out a site visit today 06.05.2020. 15.05.2020 - Site visit carried out, Landowner cleared mud from grid at entrance to pipe, Clerk reported again, providing lamp post 23 as a location. 28.05.2020 This is an update to your enquiry dated 15/05/2020 in relation to STRAMSHALL ROAD. A highways inspector has now assessed the site you reported and arranged a non-urgent works instruction – jetting machine 20.07.2020 This is an update to your enquiry dated 15/05/2020 in relation to STRAMSHALL ROAD. Works have taken place in response to your report. Other works in the area might still be pending and any unresolved defects will continue to be monitored via our routine safety inspections. reopened 20.01.2021 Clerk took photos of the flood water on the road and reported the issue again. The landowner believes that Lamp post 23 has been installed through the drain and that is why it is going onto the road, not through the drain included map of drains for the area with report.				20.07.2020	1 '
report 4224656 Reopened 20.01.2021 Reopened 20.01.2021 Trevor Mellor will carry out a site visit today 06.05.2020. 15.05.2020 - Site visit carried out, Landowner cleared mud from grid at entrance to pipe, Clerk reported again, providing lamp post 23 as a location. 28.05.2020 This is an update to your enquiry dated 15/05/2020 in relation to STRAMSHALL ROAD. A highways inspector has now assessed the site you reported and arranged a non-urgent works instruction – jetting machine 20.07.2020 This is an update to your enquiry dated 15/05/2020 in relation to STRAMSHALL ROAD. Works have taken place in response to your report. Other works in the area might still be pending and any unresolved defects will continue to be monitored via our routine safety inspections. reopened 20.01.2021 Clerk took photos of the flood water on the road and reported the issue again. The landowner believes that Lamp post 23 has been installed through the drain and that is why it is going onto the road, not through the drain. included map of drains for the area with report. Road sign broken A50 – A518 junction				20.07.2020	resolved. However; if you believe there is still an
4224656 Reopened 20.01.2021 Reopened 20.01.2021 Trevor Mellor will carry out a site visit today 06.05.2020. 15.05.2020 - Site visit carried out, Landowner cleared mud from grid at entrance to pipe, Clerk reported again, providing lamp post 23 as a location. 28.05.2020 This is an update to your enquiry dated 15/05/2020 in relation to STRAMSHALL ROAD. A highways inspector has now assessed the site you reported and arranged a non-urgent works instruction – jetting machine 20.07.2020 This is an update to your enquiry dated 15/05/2020 in relation to STRAMSHALL ROAD. Works have taken place in response to your report. Other works in the area might still be pending and any unresolved defects will continue to be monitored via our routine safety inspections. reopened 20.01.2021 Clerk took photos of the flood water on the road and reported the issue again. The landowner believes that Lamp post 23 has been installed through the drain and that is why it is going onto the road, not through the drain included map of drains for the area with report. Road sign broken A50 – A518 junction				Closed	issue that requires attention may we kindly ask
Reopened 20.01.2021 Sent to Councillors 22.04.2020 Trevor Mellor will carry out a site visit today 06.05.2020. 15.05.2020 - Site visit carried out, Landowner cleared mud from grid at entrance to pipe, Clerk reported again, providing lamp post 23 as a location. 28.05.2020 This is an update to your enquiry dated 15/05/2020 in relation to STRAMSHALL ROAD. A highways inspector has now assessed the site you reported and arranged a non-urgent works instruction – jetting machine 20.07.2020 This is an update to your enquiry dated 15/05/2020 in relation to STRAMSHALL ROAD. Works have taken place in response to your report. Other works in the area might still be pending and any unresolved defects will continue to be monitored via our routine safety inspections. reopened 20.01.2021 Clerk took photos of the flood water on the road and reported the issue again. The landowner believes that Lamp post 23 has been installed through the drain and that is why it is going onto the road, not through the drain. Included map of drains for the area with report.			report		that you contact us again with your reference
Trevor Mellor will carry out a site visit today 06.05.2020. 15.05.2020 - Site visit carried out, Landowner cleared mud from grid at entrance to pipe, Clerk reported again, providing lamp post 23 as a location. 28.05.2020 This is an update to your enquiry dated 15/05/2020 in relation to STRAMSHALL ROAD. A highways inspector has now assessed the site you reported and arranged a non-urgent works instruction – jetting machine 20.07.2020 This is an update to your enquiry dated 15/05/2020 in relation to STRAMSHALL ROAD. Works have taken place in response to your report. Other works in the area might still be pending and any unresolved defects will continue to be monitored via our routine safety inspections. reopened 20.01.2021 Clerk took photos of the flood water on the road and reported the issue again. The landowner believes that Lamp post 23 has been installed through the drain and that is why it is going onto the road, not through the drain included map of drains for the area with report. Road sign broken A50 – A518 junction			4224656		number so that we can verify the location details.
Trevor Mellor will carry out a site visit today 06.05.2020. 15.05.2020 - Site visit carried out, Landowner cleared mud from grid at entrance to pipe, Clerk reported again, providing lamp post 23 as a location. 28.05.2020 This is an update to your enquiry dated 15/05/2020 in relation to STRAMSHALL ROAD. A highways inspector has now assessed the site you reported and arranged a non-urgent works instruction – jetting machine 20.07.2020 This is an update to your enquiry dated 15/05/2020 in relation to STRAMSHALL ROAD. Works have taken place in response to your report. Other works in the area might still be pending and any unresolved defects will continue to be monitored via our routine safety inspections. reopened 20.01.2021 Clerk took photos of the flood water on the road and reported the issue again. The landowner believes that Lamp post 23 has been installed through the drain and that is why it is going onto the road, not through the drain and that is why it is going onto the road, not through the drain Included map of drains for the area with report. Road sign broken A50 – A518 junction				· ·	Sent to Councillors 22.04.2020
06.05.2020. 15.05.2020 - Site visit carried out, Landowner cleared mud from grid at entrance to pipe, Clerk reported again, providing lamp post 23 as a location. 28.05.2020 This is an update to your enquiry dated 15/05/2020 in relation to STRAMSHALL ROAD. A highways inspector has now assessed the site you reported and arranged a non-urgent works instruction – jetting machine 20.07.2020 This is an update to your enquiry dated 15/05/2020 in relation to STRAMSHALL ROAD. Works have taken place in response to your report. Other works in the area might still be pending and any unresolved defects will continue to be monitored via our routine safety inspections. reopened 20.01.2021 Clerk took photos of the flood water on the road and reported the issue again. The landowner believes that Lamp post 23 has been installed through the drain and that is why it is going onto the road, not through the drain included map of drains for the area with report.				20.01.2021	Trevor Mellor will carry out a site visit today
cleared mud from grid at entrance to pipe, Clerk reported again, providing lamp post 23 as a location. 28.05.2020 This is an update to your enquiry dated 15/05/2020 in relation to STRAMSHALL ROAD. A highways inspector has now assessed the site you reported and arranged a non-urgent works instruction – jetting machine 20.07.2020 This is an update to your enquiry dated 15/05/2020 in relation to STRAMSHALL ROAD. Works have taken place in response to your report. Other works in the area might still be pending and any unresolved defects will continue to be monitored via our routine safety inspections. reopened 20.01.2021 Clerk took photos of the flood water on the road and reported the issue again. The landowner believes that Lamp post 23 has been installed through the drain and that is why it is going onto the road, not through the drain. Included map of drains for the area with report. Road sign broken A50 – A518 junction					1
cleared mud from grid at entrance to pipe, Clerk reported again, providing lamp post 23 as a location. 28.05.2020 This is an update to your enquiry dated 15/05/2020 in relation to STRAMSHALL ROAD. A highways inspector has now assessed the site you reported and arranged a non-urgent works instruction – jetting machine 20.07.2020 This is an update to your enquiry dated 15/05/2020 in relation to STRAMSHALL ROAD. Works have taken place in response to your report. Other works in the area might still be pending and any unresolved defects will continue to be monitored via our routine safety inspections. reopened 20.01.2021 Clerk took photos of the flood water on the road and reported the issue again. The landowner believes that Lamp post 23 has been installed through the drain and that is why it is going onto the road, not through the drain. Included map of drains for the area with report.					15.05.2020 - Site visit carried out. Landowner
reported again, providing lamp post 23 as a location. 28.05.2020 This is an update to your enquiry dated 15/05/2020 in relation to STRAMSHALL ROAD. A highways inspector has now assessed the site you reported and arranged a non-urgent works instruction – jetting machine 20.07.2020 This is an update to your enquiry dated 15/05/2020 in relation to STRAMSHALL ROAD. Works have taken place in response to your report. Other works in the area might still be pending and any unresolved defects will continue to be monitored via our routine safety inspections. reopened 20.01.2021 Clerk took photos of the flood water on the road and reported the issue again. The landowner believes that Lamp post 23 has been installed through the drain and that is why it is going onto the road, not through the drain. Included map of drains for the area with report. Road sign broken A50 – A518 junction					
28.05.2020 This is an update to your enquiry dated 15/05/2020 in relation to STRAMSHALL ROAD. A highways inspector has now assessed the site you reported and arranged a non-urgent works instruction – jetting machine 20.07.2020 This is an update to your enquiry dated 15/05/2020 in relation to STRAMSHALL ROAD. Works have taken place in response to your report. Other works in the area might still be pending and any unresolved defects will continue to be monitored via our routine safety inspections. reopened 20.01.2021 Clerk took photos of the flood water on the road and reported the issue again. The landowner believes that Lamp post 23 has been installed through the drain and that is why it is going onto the road, not through the drain. Included map of drains for the area with report. Road sign broken A50 – A518 junction 15.07.2020 4205119 17.07.2020 Clir provided photo of broken sign					
This is an update to your enquiry dated 15/05/2020 in relation to STRAMSHALL ROAD. A highways inspector has now assessed the site you reported and arranged a non-urgent works instruction – jetting machine 20.07.2020 This is an update to your enquiry dated 15/05/2020 in relation to STRAMSHALL ROAD. Works have taken place in response to your report. Other works in the area might still be pending and any unresolved defects will continue to be monitored via our routine safety inspections. reopened 20.01.2021 Clerk took photos of the flood water on the road and reported the issue again. The landowner believes that Lamp post 23 has been installed through the drain and that is why it is going onto the road, not through the drain. Included map of drains for the area with report. Road sign broken A50 – A518 junction					location.
This is an update to your enquiry dated 15/05/2020 in relation to STRAMSHALL ROAD. A highways inspector has now assessed the site you reported and arranged a non-urgent works instruction – jetting machine 20.07.2020 This is an update to your enquiry dated 15/05/2020 in relation to STRAMSHALL ROAD. Works have taken place in response to your report. Other works in the area might still be pending and any unresolved defects will continue to be monitored via our routine safety inspections. reopened 20.01.2021 Clerk took photos of the flood water on the road and reported the issue again. The landowner believes that Lamp post 23 has been installed through the drain and that is why it is going onto the road, not through the drain. Included map of drains for the area with report. Road sign broken A50 – A518 junction To 7.2020 Clir provided photo of broken sign					28.05.2020
15/05/2020 in relation to STRAMSHALL ROAD. A highways inspector has now assessed the site you reported and arranged a non-urgent works instruction – jetting machine 20.07.2020 This is an update to your enquiry dated 15/05/2020 in relation to STRAMSHALL ROAD. Works have taken place in response to your report. Other works in the area might still be pending and any unresolved defects will continue to be monitored via our routine safety inspections. reopened 20.01.2021 Clerk took photos of the flood water on the road and reported the issue again. The landowner believes that Lamp post 23 has been installed through the drain and that is why it is going onto the road, not through the drain. Included map of drains for the area with report. Road sign broken A50 – A518 junction					
you reported and arranged a non-urgent works instruction – jetting machine 20.07.2020 This is an update to your enquiry dated 15/05/2020 in relation to STRAMSHALL ROAD. Works have taken place in response to your report. Other works in the area might still be pending and any unresolved defects will continue to be monitored via our routine safety inspections. reopened 20.01.2021 Clerk took photos of the flood water on the road and reported the issue again. The landowner believes that Lamp post 23 has been installed through the drain and that is why it is going onto the road, not through the drain. Included map of drains for the area with report. Road sign broken A50 – A518 junction					
you reported and arranged a non-urgent works instruction – jetting machine 20.07.2020 This is an update to your enquiry dated 15/05/2020 in relation to STRAMSHALL ROAD. Works have taken place in response to your report. Other works in the area might still be pending and any unresolved defects will continue to be monitored via our routine safety inspections. reopened 20.01.2021 Clerk took photos of the flood water on the road and reported the issue again. The landowner believes that Lamp post 23 has been installed through the drain and that is why it is going onto the road, not through the drain. Included map of drains for the area with report. Road sign broken A50 – A518 junction					A highways inspector has now assessed the site
instruction – jetting machine 20.07.2020 This is an update to your enquiry dated 15/05/2020 in relation to STRAMSHALL ROAD. Works have taken place in response to your report. Other works in the area might still be pending and any unresolved defects will continue to be monitored via our routine safety inspections. reopened 20.01.2021 Clerk took photos of the flood water on the road and reported the issue again. The landowner believes that Lamp post 23 has been installed through the drain and that is why it is going onto the road, not through the drain. Included map of drains for the area with report. Road sign broken A50 – A518 junction					
This is an update to your enquiry dated 15/05/2020 in relation to STRAMSHALL ROAD. Works have taken place in response to your report. Other works in the area might still be pending and any unresolved defects will continue to be monitored via our routine safety inspections. reopened 20.01.2021 Clerk took photos of the flood water on the road and reported the issue again. The landowner believes that Lamp post 23 has been installed through the drain and that is why it is going onto the road, not through the drain. Included map of drains for the area with report. Road sign broken A50 – A518 junction 15.07.2020 4205119 17.07.2020 Cllr provided photo of broken sign					
This is an update to your enquiry dated 15/05/2020 in relation to STRAMSHALL ROAD. Works have taken place in response to your report. Other works in the area might still be pending and any unresolved defects will continue to be monitored via our routine safety inspections. reopened 20.01.2021 Clerk took photos of the flood water on the road and reported the issue again. The landowner believes that Lamp post 23 has been installed through the drain and that is why it is going onto the road, not through the drain. Included map of drains for the area with report. Road sign broken A50 – A518 junction 15.07.2020 4205119 17.07.2020 Cllr provided photo of broken sign					
15/05/2020 in relation to STRAMSHALL ROAD. Works have taken place in response to your report. Other works in the area might still be pending and any unresolved defects will continue to be monitored via our routine safety inspections. reopened 20.01.2021 Clerk took photos of the flood water on the road and reported the issue again. The landowner believes that Lamp post 23 has been installed through the drain and that is why it is going onto the road, not through the drain. Included map of drains for the area with report. Road sign broken A50 – A518 junction 15.07.2020 4205119 17.07.2020 Cllr provided photo of broken sign					20.07.2020
report. Other works in the area might still be pending and any unresolved defects will continue to be monitored via our routine safety inspections. reopened 20.01.2021 Clerk took photos of the flood water on the road and reported the issue again. The landowner believes that Lamp post 23 has been installed through the drain and that is why it is going onto the road, not through the drain. Included map of drains for the area with report. Road sign broken A50 – A518 junction 15.07.2020 A205119 17.07.2020 Cllr provided photo of broken sign					
report. Other works in the area might still be pending and any unresolved defects will continue to be monitored via our routine safety inspections. reopened 20.01.2021 Clerk took photos of the flood water on the road and reported the issue again. The landowner believes that Lamp post 23 has been installed through the drain and that is why it is going onto the road, not through the drain. Included map of drains for the area with report. Road sign broken A50 – A518 junction 15.07.2020 A205119 17.07.2020 Cllr provided photo of broken sign					Works have taken place in response to your
pending and any unresolved defects will continue to be monitored via our routine safety inspections. reopened 20.01.2021 Clerk took photos of the flood water on the road and reported the issue again. The landowner believes that Lamp post 23 has been installed through the drain and that is why it is going onto the road, not through the drain. Included map of drains for the area with report. Road sign broken A50 – A518 junction 15.07.2020 4205119 17.07.2020 Cllr provided photo of broken sign					
to be monitored via our routine safety inspections. reopened 20.01.2021 Clerk took photos of the flood water on the road and reported the issue again. The landowner believes that Lamp post 23 has been installed through the drain and that is why it is going onto the road, not through the drain. Included map of drains for the area with report. Road sign broken A50 – A518 junction 15.07.2020 4205119 17.07.2020 Cllr provided photo of broken sign					
inspections. reopened 20.01.2021 Clerk took photos of the flood water on the road and reported the issue again. The landowner believes that Lamp post 23 has been installed through the drain and that is why it is going onto the road, not through the drain. Included map of drains for the area with report. Road sign broken A50 – A518 junction Included map of Cllr provided photo of broken sign					
Clerk took photos of the flood water on the road and reported the issue again. The landowner believes that Lamp post 23 has been installed through the drain and that is why it is going onto the road, not through the drain. Included map of drains for the area with report. Road sign broken A50 – A518 junction Clerk took photos of the flood water on the road and reported the issue again. The landowner believes that Lamp post 23 has been installed through the drain and that is why it is going onto the road, not through the area with report.					_
Clerk took photos of the flood water on the road and reported the issue again. The landowner believes that Lamp post 23 has been installed through the drain and that is why it is going onto the road, not through the drain. Included map of drains for the area with report. Road sign broken A50 – A518 junction Clerk took photos of the flood water on the road and reported the issue again. The landowner believes that Lamp post 23 has been installed through the drain and that is why it is going onto the road, not through the area with report.					reopened 20.01.2021
and reported the issue again. The landowner believes that Lamp post 23 has been installed through the drain and that is why it is going onto the road, not through the drain. Included map of drains for the area with report. Road sign broken A50 – A518 junction 15.07.2020 4205119 17.07.2020 Cllr provided photo of broken sign					
believes that Lamp post 23 has been installed through the drain and that is why it is going onto the road, not through the drain. Included map of drains for the area with report. Road sign broken A50 – A518 junction Delieves that Lamp post 23 has been installed through the drain and that is why it is going onto the road, not through the drain. Included map of drains for the area with report. Cllr provided photo of broken sign					
through the drain and that is why it is going onto the road, not through the drain. Included map of drains for the area with report. Road sign broken A50 – A518 junction 15.07.2020 4205119 17.07.2020 Cllr provided photo of broken sign					
the road, not through the drain. Included map of drains for the area with report. Road sign broken A50 – A518 junction 15.07.2020 4205119 17.07.2020 Cllr provided photo of broken sign					
Road sign broken A50 – A518 junction drains for the area with report. Cllr provided photo of broken sign 17.07.2020					
A50 – A518 junction					drains for the area with report.
A50 – A518 junction	Road sign broken	15.07.2020	4205119	17.07.2020	Cllr provided photo of broken sign
Dear Mrs Uttoxeter Rural Parish Council. This is	T				
					Dear Mrs Uttoxeter Rural Parish Council. This is

Nearest postcode ST14 5AA The McDonalds Bramshall Village Sign not visible as overgrown hedge on verge on industrial estate side of the village Nearest postcode Daisy Bank, Stone Road, Bramshall, ST14 8SH	4216133	23.10.2020	23.04.2021	an update to your enquiry dated 15/07/2020 in relation to A518 ASHBOURNE ROAD. A highways inspector has now assessed the site you reported and arranged a non-urgent works instruction. Checked for update on SCC Website – notes are: Your enquiry is currently allocated to a Highways officer and will be updated as soon as possible. We receive around 4000 highway related reports every month. but we have a limited number of officers to investigate and respond to these.
Bennetts Lane, gullies blocked by mud Bramshall ST14 5BN	4231297	23.02.2021	19.03.2021	This is an update to your enquiry dated 23/02/2021 in relation to BENNETTS LANE. A highways officer has now considered your enquiry and added the following notes to your report: Thank you for your enquiry work has already been raised for multiple gullies in this location and will be carried out as soon as scheduling and resources allow
Give Way Sign – Damaged Bennetts Lane/Stone Road, Bramshall ST14 5BG	4238240 4255484 4202868 4265245	15.04.2021	27.04.2021 17.09.2021 Reported again, new number issued 01.01.2022 Reported again 04.01.2022	Two photos sent with report, the sign will fall into the road if not repaired soon. This is an update to your enquiry dated 15/04/2021 in relation to BENNETTS LANE. A highways inspector has now assessed the site you reported and arranged a non-urgent works instruction. 17.09.2021 Reported again, as sign in danger of falling. Reported number 4202868 – reported by resident on 23.06.2021 01.01.2022 reported again, as Chairman provided two photos. This is an update to your enquiry dated 01/01/2022 in relation to BENNETTS LANE. A highways inspector has now assessed the site you reported and arranged a non-urgent works instruction.

Pavement tarmac	12.10.2021	4257847	04.11.2021	Reported by resident at October 2021 meeting.
damage, Olive Tree, High Street, STramshall ST14 5AL	12.10.202		12.04.2022	SCC updated: This is an update to your enquiry dated 12/10/2021 in relation to HIGH STREET. A highways inspector has now assessed the site you reported and arranged a non-urgent works instruction. We have not yet been able to coordinate resources to resolve the enquiry you raised, due to high demand for reactive maintenance work across our road network. We write to assure you that we have not forgotten about the issue and will endeavour to schedule the necessary works as soon as is practicably possible.
Trees obstructing visibility on Stafford Road, nearest postcode Loxley Hall School, ST14 8RS	22.10.2021	4258923		Reported by councillor in October 2021 meeting
Grit Salt bin – Salt Box requested by resident for Bramshall. Location verge on B5027/Church Lane Near The Croft driveway, Stone Road Nearest Postcode ST14 5BQ	08.12.2021	Community Grit Bin request 4275940	17.12.2021 01.02.2022 22.03.2022 14.06.2022	Resident requested, SCC advised to use Report it, so area can be accessed. If SCC says no, we can adopt a community salt bin. An assessment has been undertaken at this location and does not qualify under the winter maintenance policy for a grit bin, This area Church Lane junction of Stone Road Bramshall, Scores 60 out of the required 100 points when assessed against the winter service policy "WS7" form. Stone Road and Church Lane are both on gritting routes I am sorry that I cannot be more positive in my response. Parish Council will investigate Community Grit Bin The Parish Council voted to request a community Grit Bin in meeting 01.03.2022 Sent photos to SCC of the location — it is just after The Croft driveway.

Road Sign – direction	21.12.2021	4264631	04.01.2022	The direction arm on the Road side sign has
arm is broken -	21.12.2021	4204031	04.01.2022	broken. Photos x2 attached.
Junction of Church				
Lane and B5027				This is an update to your enquiry dated 21/12/2021 in relation to STONE ROAD.
Nearest Postcode				21/12/2021 III relation to STONE NOAD.
ST14 5BG				A highways inspector has now assessed the site
				you reported and arranged a non-urgent works instruction.
Gully Blocked	08.02.2022	4269411		Resident reported this issue via private email
Opposite Entrance of				address
The Walled Garden,				
St Michaels Road,				
Stramshall Uttoxeter ST14 5DU				
Creighton Lane, Stramshall, ST14 5AF	22.02.2022	4271697	08.03.2022	Included two photos – one with drain covered in water and the other with no water, so can see
			03.05.2022	comparison.
Flooding continues on cornor (Bridge		4280335		·
Cottage end)		120000		08.03.2022 – highways updated
,				Current Status: No Further Highways Action
				03.05.2022 - Reported again and asked if
				Landowner could be contacted, so water has
				somewhere to go – attached two photos, one o the flooding and one of the drain
Dairy Farm, High Street, Stramshall,	23.02.2022	4271842	08.03.2022	Reported with photos and map of drains in area.
ST14 5AG				This has been reported many times and SCC have
E		4276225	23. 03.2022	put cameras down, but still no resolution.
Flooding on side of road – locally it has		127 0220	25. 05.2022	
always been thought				
that Lamp Post M23 and M22 have been				08.03.2022 – update from Highways
installed through				We have visited the location provided with your
drain, hence water				report but have been unable to identify any
leaves open ditch and travels down the side				defects that require remedial works at this time.
of road to the first				No further Action
open manhole cover				Reported again on 23.03.2022
30mph signs in	15.06.2022	4285061		Requested to be put 30mph signs on lamp posts
Stramshall, from Poppits Lane all the				or other locations.
way down high street				
to Broomyclose lane				
Nearest postcode				
ST14 5AL				

Alder Bank Filling	17.06.2022	4285323		As you travel from Loxley to Stafford, the
Station postcode	.7.00.2022	1200020		· · · · · · · · · · · · · · · · ·
ST14 8RU				hedge/vegetation is on the right hand side and is
0114010				blocking visibility on the corner.
Junction of				The exact location is where the A518 has a
A518/Watery Lane				junction with Watery Lane and the overgrown
, and the second				
Overgrown vegetation				vegetation is opposite Watery Lane.
blocking visibility				The junction has a history of fatalities and
, ,				therefore the Parish Council consider this request
				to be urgent.
Lowley Hall School	17.06.2022	4285321		As you travel from Loxley Lane/Bennetts Lane to
Lowley Hall Ochool	17.00.2022	4203321		I
On A518				join the A518 (Stafford Road), the
Junction with				vegetation/hedges is blocking the visibility of
Bennetts Lane				road users and is causing a hazard.
ST14 8RS				This junction is dangerous without the visibility
				issue and the Parish Council consider this to be an
				urgent request.
Narrow Road Sign, by	22.06.2022	4285778	24.06.2022	Cllr Jones provided two pictures that were
Railway				submitted.
Crossing/Bridge on				Sastimetes.
Bennetts Lane/Loxley				A highways officer has assessed the site you
Lane – pushed over				reported and arranged a non-urgent work
and turning wrong				instruction. The outcome of the assessment
way so no one can				means this defect does not pose an immediate
see it				risk to public safety.
				risk to public surety.
				Our priority is to be effective at responding to the
				most serious problems on the network, therefore
				we are unable to provide a delivery date for
				defects of a non-urgent nature, until such time
				that resources become available.
				Charlesources become available.
Spath Roundabout	29.07.2022	4289581		Clerk reported to MJ Barretts and they requested
B5030 /A518 meet in		Signs		reporting to SCC, as they only cut grass and
Spath		4289585		significant damage to the trees has occurred.
pine trees damaged		tree damage		Reported as two, the signage damage and the
and road signs				tree damage
damaged				
-				