0300 111 8000 press 1

www.staffordshire.gov.uk/reportit highways@staffordshire.gov.uk

Salting and gritting map

https://www.staffordshire.gov.uk/transport/staffshighways/winterdriving/salting/Saltingroutes.aspx

location and requested action reported requested action and requested and update. 15.04.2015 15.04.2015 15.05.	Reported issue –	Date	Highways	Follow up	Comments
Beamhurst Bridge opposite Stramshall Mill Farm, ST14 5DU, coping stone dislodged, needs cementing into place 15.04.2015 15.242129 15.05.2015 15.05.2015 15.05.2015 18.12.2017 19.12.2016 19.10.2018 19.10				•	
Beamhurst Bridge opposite Stramshall Mill Farm, ST14 5DL, coping stone dislodged, needs cementing into place 15.04.2016 4058873					
Junction of stocks lane and Stone Lane 4139163 4139163 24.06.2016 ST14 5NE 4139163 24.06.2016 10.08.2016 20.09.2016 28.02.2017 Received e-mail saying they would review it again, then another one to say 13.09.2017 13.09.2017 13.09.2017 13.09.2017 14.04.2017 15.02018 16.10.2018 19.10.2018 10.04.2016 24.06.2016 26.00.2016 26.00.2017 27.00.2018 28.02.2017 20.09.2016	Beamhurst Bridge opposite Stramshall Mill Farm, ST14 5DU, coping stone dislodged, needs cementing into	15.04.2015	15242129	15.05.2015 03.11.2015 27.11.2015 18.12.2015 26.01.2016 01.03.2016 24.06.2016 10.08.2016 20.09.2016 03.02.2017 22.08.2017 03.12.2017 12.12.2017	Was re-inspected w/c 9th November, still waiting for an update by engineers. No update Bridge was inspected, works will be carried out, low priority. Still low priority at present. System down today Still low priority Sending note to the scheduling team, given a new reference number as no job has been raised on old system. Phone call from highways, they have reviewed the coping stones and will fit it into next financial year budget. This was closed on 22.02.2017, she will open it again and send it back to Chris to have another look. Report sent from engineering, Tom to view the bridge from. Still low priority, will be completed when time is
Junction of stocks lane and Stone Lane 4043863 4139163 24.06.2016 ST14 5NE 4043863 4139163 24.06.2016 10.08.2016 10.08.2016 20.09.2016 28.02.2017 Reported it again, but with photos of the junction this time 14.04.2017 Received e-mail saying they would review it again, then another one to say 13.09.2017 13.09.2017 13.09.2017 14.04.2017 15.00.07.2018 16.10.2018 19.10.2018 10.08.2016 10.08.2	Stocks Lane	05.04.2016	4043109	05.04.2016	· -
Lane ST14 5NE 4139163 24.06.2016 10.08.2016 10.08.2016 28.02.2017 Reported it again, but with photos of the junction this time 14.04.2017 Received e-mail saying they would review it again, then another one to say 13.09.2017 13.09.2017 The severity of the reported issue has been determined by a number of factors which include the defect's location, size and ultimately, the risk the defect poses to public safety. 16.10.2018 19.10.2018 19.10.2018 10.08.2016 10.08.2016 Reported it again, but with photos of the junction this time 14.04.2017 Received e-mail saying they would review it again, then another one to say 13.09.2017 The severity of the reported issue has been determined by a number of factors which include the defect's location, size and ultimately, the risk the defect poses to public safety. The identified defects are not considered to be high risk and the necessary repairs will be grouped with similar works in the area to be as efficient and cost effective as possible. Currently over 50% of these repairs are taking			4043863	12.04.2016	
ST14 5NE 10.08.2016 10.08.2016 10.08.2016 The remaining identified defects on the county's highway network are completed as soon as resources allow. 28.02.2017 Reported it again, but with photos of the junction this time 14.04.2017 Received e-mail saying they would review it again, then another one to say 13.09.2017 The severity of the reported issue has been determined by a number of factors which include the defect's location, size and ultimately, the risk the defect poses to public safety. 16.10.2018 16.10.2018 19.10.2018 The remaining identified defects on the county's highway network are completed as soon as resources allow. Reported it again, but with photos of the junction this time 10.08.2017 Received e-mail saying they would review it again, then another one to say The severity of the reported issue has been determined by a number of factors which include the defect's location, size and ultimately, the risk the defect poses to public safety. The identified defects are not considered to be high risk and the necessary repairs will be grouped with similar works in the area to be as efficient and cost effective as possible. Currently over 50% of these repairs are taking			4139163	24.06.2016	
28.02.2017 Reported it again, but with photos of the junction this time 14.04.2017 Received e-mail saying they would review it again, then another one to say 13.09.2017 The severity of the reported issue has been determined by a number of factors which include the defect's location, size and ultimately, the risk the defect poses to public safety. 16.10.2018 The identified defects are not considered to be high risk and the necessary repairs will be grouped with similar works in the area to be as efficient and cost effective as possible. Currently over 50% of these repairs are taking	ST14 5NE			10.08.2016	The remaining identified defects on the county's
time 14.04.2017 Received e-mail saying they would review it again, then another one to say 13.09.2017 The severity of the reported issue has been determined by a number of factors which include the defect's location, size and ultimately, the risk the defect poses to public safety. The identified defects are not considered to be high risk and the necessary repairs will be grouped with similar works in the area to be as efficient and cost effective as possible. Currently over 50% of these repairs are taking				20.09.2016	allow.
Received e-mail saying they would review it again, then another one to say 13.09.2017 The severity of the reported issue has been determined by a number of factors which include the defect's location, size and ultimately, the risk the defect poses to public safety. 16.10.2018 The identified defects are not considered to be high risk and the necessary repairs will be grouped with similar works in the area to be as efficient and cost effective as possible. Currently over 50% of these repairs are taking				28.02.2017	
13.09.2017 The severity of the reported issue has been determined by a number of factors which include the defect's location, size and ultimately, the risk the defect poses to public safety. 16.10.2018 The identified defects are not considered to be high risk and the necessary repairs will be grouped with similar works in the area to be as efficient and cost effective as possible. Currently over 50% of these repairs are taking				14.04.2017	Received e-mail saying they would review it again, then
by a number of factors which include the defect's location, size and ultimately, the risk the defect poses to public safety. The identified defects are not considered to be high risk and the necessary repairs will be grouped with similar works in the area to be as efficient and cost effective as possible. Currently over 50% of these repairs are taking				22.08.2017	another one to say
03.11.2017 location, size and ultimately, the risk the defect poses to public safety. The identified defects are not considered to be high risk and the necessary repairs will be grouped with similar works in the area to be as efficient and cost effective as possible. Currently over 50% of these repairs are taking				13.09.2017	
16.10.2018 16.10.2018 The identified defects are not considered to be high risk and the necessary repairs will be grouped with similar works in the area to be as efficient and cost effective as possible. Currently over 50% of these repairs are taking				03.11.2017	location, size and ultimately, the risk the defect poses to
16.10.2018 and the necessary repairs will be grouped with similar works in the area to be as efficient and cost effective as possible. Currently over 50% of these repairs are taking				02.07.2018	
possible. Currently over 50% of these repairs are taking				16.10.2018	and the necessary repairs will be grouped with similar
Diace Within Ou days. The remaining identified defects				19.10.2018	possible. Currently over 50% of these repairs are taking

Speed hump — request a new one be installed on the	06.09.2016	4057434	20.09.2016 28.02.2017	on the county's highway network are completed as soon as resources allow. 14th April, work note has been raised now. No ETA The 7 pot holes are CAT3 so no ETA Still on scheduling team waiting list Still awaiting scheduling Still to be scheduled, but will re raise it with scheduling team today 22.08.2017 Clerk removed loose tarmac from the road and took it to the recycling centre, as causing a hazard. Parish Council meeting advised that these pot holes have had white paint markings, so repair could be soon. Clerk called Highways and asked for an update – they have a job on the system, clerk advised still a CAT3 so will do when in the area. Clerk asked for an update by the Scheduling Team – they need to have a multi way lights to carry out the repairs this is causing the delay. No date. Clerk took 2 more photos of potholes 16.10.2018 and submitted them again to highways and sent email to Clir Deaville, copied Chair and Vice Chair into email. 19.10.2018 - This is an update to your enquiry dated 16/10/2018 in relation to STOCKS LANE. A highways inspector has now assessed the site and arranged for repairs to be carried out. The reported issue is not considered to be a high risk to public safety and so the repairs will be grouped with similar works in the area in order to be as efficient and cost effective as possible. Currently over 50% of these repairs take place within 60 days. The remaining defects are repaired as soon as resources are available. Sent request to the County Councillor for the area, this will be discussed at the highways meeting
-			28.02.2017 01.03.2017 01.11.2018	This was sent on 19.09.2016 it was sent to Division Highways Programme meeting to be discussed. Highways Liaison person is Philip Atkins, so need update from him.
ST14 5AQ				28.02.2017 Clerk e-mailed Philip Atkins for an update and updated resident by telephone call

	1		I	O4 O2 2047 - good greatered from Phillip Adding
				01.03.2017 e-mail received from Philip Atkins
				Dear Ginny
				It is in the DHP for consideration but waiting for funding
				through s106 monies when the new JCB factory is built.
				Regards
				Philip
				Philip Atkins OBE
				This request could be included in the Stramshall S106
				funding plan, Cllr Oulsnam to consider
Pot hole and flattened	21.10.2017	4094161	24.10.2017	Sent photo of large pot hole and flattened black and
black/white posts			01.03.2018	white posts.
on corner of A522/Waterloo			23.05.2018	
Farm, Pigeonhay Lane, Beamhurst,			01.11.2018	
ST14 5dy				38
				mucini
				This is an update to your enquiry dated 21/10/2017 in
				relation to PIGEONHAY LANE.
				A highways inspector has now assessed the site and
				arranged for repairs to be carried out. The reported issue is not considered to be a high risk to
				public safety and so the repairs will be grouped with
				similar works in the area in order to be as efficient and cost effective as possible. Currently over 50% of these
				repairs take place within 60 days. The remaining defects
				are repaired as soon as resources are available.
				Scc website says still waiting on a response from schedulers.
				The website now says
				Current Status Reached: 23rd October, 2017 (11:34 am)
				Fault categorised by inspector. Awaiting works to fix the
				fault.
				23rd October, 2017 (11:34 am)
				Waiting for inspector to visit site
				01.11.2018 – clerk called highways for an update, as
				noticed this still not completed – scheduling team
				advised they will highlight it
17 pot holes from	21.10.2017	4094165	24.10.2017	This is an update to your enquiry dated 21/10/2017 in
32 Broomyclose	21.10.2017	100 1100		relation to BROOMYCLOSE LANE.
lane ST14 5AN down FARM			01.03.2018	
LANE towards the				A highways inspector has now assessed the site and arranged for repairs to be carried out.
	<u> </u>		<u> </u>	aagea for repairs to be carried out.

	1	ī	T	T
playing fields ST14 5AX			01.11.2018	The reported issue is not considered to be a high risk to public safety and so the repairs will be grouped with similar works in the area in order to be as efficient and cost effective as possible. Currently over 50% of these repairs take place within 60 days. The remaining defects are repaired as soon as resources are available. Fault categorised by inspector. Awaiting works to fix the fault. 01.11.2018 - Clerk contacted highways, scheduling team
				will be highlighted it.
Gullies by Springfield Hse, Stramshall, ST14 5DU blocked	18.09.2018	4136376		Clerk requested that it be put on the regular maintenance report on Highways.
B5030 -	28.02.2017	4076870	28.03.2017	Clerk requested highways to clear verge, advised it is
Quarry Road Sign Blocked with Trees.		4136473	02.05.2017 14.09.2018 19.09.2018	land owner, which is Aggregate Industries. Aggregate Industries advised it is Highways, Highways have written to land owner Submitted a new request for trees to be cut to highways
Location - Coming from Rocester on the B5030, it's the large information board on the approach to the roundabout which show roads for Uttoxeter Stafford A518, or ahead for Stoke ,Derby A50,M6 North. The land is the house near to it is			02.10.2018	This is an update to your enquiry dated 19/09/2018 in relation to ASHBOURNE ROAD. A highways inspector has now visited the site and added the following notes to the report: Letter sent out in post to landowner 01.10.2018 JK Clerk sent an email to Aggregate Industries including the comments from Highways.
Spath Cottage its opposite Staffordshire Traditional Meats				
Cllr Mark Deaville	19.09.2018			Sent an email to Cllr Deaville at SCC asking him to consider the request for traffic count on so that speeding cars on Abbotts Bromley Road can be monitored. Also asked for an update on all issues on highways log that have been reported for over 60 days.
Weak Bridge, by Springfields House, St Michaels Road, Stramshall ST14 5DU crash on	21.09.2018	4136870	28.09.2018 02.10.2018	Cllr Oulsnan reported bridge accident to me, called Highways and reported it as urgent. The repairs to bridge will take 3 months

20.09.2018 happened, 5m of bridge in river				
Flower Pots on Highways pavement, Old Smithy, Stone Road, Bramshall, ST14 5BG	28.09.2018	4137634	16.10.2018	Sent highways photos of the flower pots on the highway pavement and asked to investigate. This is an update to your enquiry dated 28/09/2018 in relation to STONE ROAD. A highways inspector has now visited the site and added the following notes to the report: The issue you have reported is not within the public highway and we believe the area to be privately owned. Therefore, the County Council is not in a position to investigate the issue you have raised. However, should you wish to pursue this matter, you can contact Land Registry to identify the landowner using the following website: https://www.gov.uk/government/organisations/land-registry
BT ducking reel left by Spath layby ST14 5AD	24.10.2018 26.10.2018	Wm1muy64		BT Openreach 0800 023 2023 contacted as ESBC will not collect
Reported to BT Openreach				