


URPC Highways Reporting Log –2022

All issues were reported to Staffordshire County Council via the Report It function

www.staffordshire.gov.uk/reportit

Salting and gritting map

<https://www.staffordshire.gov.uk/transport/staffshighways/winterdriving/salting/Saltingroutes.aspx>

Reported issue – location and requested action	Date reported	Highways reference number	Follow up date	Comments
Speed hump – request a new one be installed on the corner of St Michaels Road, Cedar Drive and Hollington Lane, Stramshall ST14 5AQ	06.09.2016	4057434	20.09.2016 28.02.2017 01.03.2017 01.11.2018 09.11.2019 19.03.2021	This request could be included in the Stramshall S106 funding plan, Cllr Oulsnam to consider included in site visit with SCC, but no plans to be issued until after April 2020. Plans for S106 will be with Parish Council by Summer 2021
Pot hole and flattened black/white posts on corner of A522/Waterloo Farm, Pigeonhay Lane, Beamhurst, ST14 5dy	21.10.2017	4094161 4201024	24.10.2017 01.03.2018 23.05.2018 01.11.2018 20.02.2019 10.06.2020 24.07.2020 19.01.2022	Sent photo of large pot hole and flattened black and white posts.  01.11.2018 – clerk called highways for an update, as noticed this still not completed – scheduling team advised they will highlight it 20.02.2019 – this is with the scheduling team, as a CAT 3 10.06.2020 Reported again, as main road has been repaired, but this is still on their system as awaiting scheduling team. 24.07.2020 This is an update to your enquiry dated 10/06/2020 in relation to PIGEONHAY LANE. A highways inspector has now assessed the site you reported and arranged a non-urgent works instruction. 19.01.2022 – received an email from SCC to say this issue is on going.

<p>The Cedars Hollington Lane STramshall</p> <p>ST14 5AJ</p> <p>guttering installed and water being discharged onto the road</p>	28.01.2020	4186841		Resident reported it and provided photos
<p>Flooding on Road, blocked culvert under road.</p> <p>Dairy Farm, High Street, Stramshall, ST14 5AG</p> <p>Lamp post 23 Lamp post 22</p>	10.04.2020	<p>4196935</p> <p>Reported again</p> <p>4198897</p> <p>New Ref for 20.01.2021 report</p> <p>4224656</p>	<p>22.04.2020</p> <p>06.05.2020</p> <p>15.05.2020</p> <p>28.05.2020</p> <p>20.07.2020</p> <p>Closed</p> <p>Reopened 20.01.2021</p>	<p>Map included of area, with arrow to culvert and map of drains in the area.</p> <p>This is an update to your enquiry dated 10/04/2020 in relation to HIGH STREET.</p> <p>A highways officer has now considered your enquiry and added the following notes to your report: We have visited the location provided with your report but have been unable to identify any defects that require remedial works at this time. It might be that the problem has now been resolved. However; if you believe there is still an issue that requires attention may we kindly ask that you contact us again with your reference number so that we can verify the location details.</p> <p>Sent to Councillors 22.04.2020</p> <p>Trevor Mellor will carry out a site visit today 06.05.2020.</p> <p>15.05.2020 - Site visit carried out, Landowner cleared mud from grid at entrance to pipe, Clerk reported again, providing lamp post 23 as a location.</p> <p>28.05.2020 This is an update to your enquiry dated 15/05/2020 in relation to STRAMSHALL ROAD.</p> <p>A highways inspector has now assessed the site you reported and arranged a non-urgent works instruction – jetting machine</p> <p>20.07.2020 This is an update to your enquiry dated 15/05/2020 in relation to STRAMSHALL ROAD .</p> <p>Works have taken place in response to your report. Other works in the area might still be pending and any unresolved defects will continue to be monitored via our routine safety inspections.</p> <p>reopened 20.01.2021</p>

				Clerk took photos of the flood water on the road and reported the issue again. The landowner believes that Lamp post 23 has been installed through the drain and that is why it is going onto the road, not through the drain. Included map of drains for the area with report.
Road sign broken A50 – A518 junction Nearest postcode ST14 5AA The McDonalds	15.07.2020	4205119	17.07.2020	<p>CLlr provided photo of broken sign</p> <p>Dear Mrs Uttoxeter Rural Parish Council. This is an update to your enquiry dated 15/07/2020 in relation to A518 ASHBOURNE ROAD.</p> <p>A highways inspector has now assessed the site you reported and arranged a non-urgent works instruction.</p>
Bramshall Village Sign not visible as overgrown hedge on verge on industrial estate side of the village Nearest postcode Daisy Bank, Stone Road, Bramshall, ST14 8SH	4216133	23.10.2020	23.04.2021	<p>Checked for update on SCC Website – notes are:</p> <p>Your enquiry is currently allocated to a Highways officer and will be updated as soon as possible. We receive around 4000 highway related reports every month. but we have a limited number of officers to investigate and respond to these.</p>
<p>Broomyclose Lane, towards Creighton Lane end. Nearest postcode is for Bridge Cottage, but this is on Creighton Lane. ST14 5AX</p> <p>The road is a single track that runs from the main Broomyclose Lane down towards Creighton Lane, Stramshall playing fields,</p> <p>The single track road has a number of pot holes and surface dressing has deteriorated.</p>	4216136	23.10.2020	25.11.2020	<p>This is an update to your enquiry dated 23/10/2020 in relation to BROOMYCLOSE LANE</p> <p>A highways officer has now considered your enquiry and added the following notes to your report:</p> <p>Thank you for your enquiry.</p> <p>All roads connected to Staffordshire's highway network are routinely inspected to identify safety defects. Any issues that are identified are raised for repair and categorised according to urgency.</p> <p>Work has already been raised for multiple defects at this location. If you wish to report a specific defect please contact us with a location and description of the defect that you are reporting</p> <p>If you have any queries on the response you have received, further information on how we respond to commonly reported highway issues, as well as frequently asked questions; are available on the 'Report It Explained' page under the Highways section of our website at www.staffordshire.gov.uk</p>

Bennetts Lane, gullies blocked by mud Bramshall ST14 5BN	4231297	23.02.2021	19.03.2021	<p>This is an update to your enquiry dated 23/02/2021 in relation to BENNETTS LANE.</p> <p>A highways officer has now considered your enquiry and added the following notes to your report:</p> <p>Thank you for your enquiry work has already been raised for multiple gullies in this location and will be carried out as soon as scheduling and resources allow</p>
Give Way Sign – Damaged Bennetts Lane/Stone Road, Bramshall ST14 5BG	4238240 4255484 4202868 4265245	15.04.2021	27.04.2021 17.09.2021 Reported again, new number issued 01.01.2022 Reported again 04.01.2022	<p>Two photos sent with report, the sign will fall into the road if not repaired soon.</p> <p>This is an update to your enquiry dated 15/04/2021 in relation to BENNETTS LANE.</p> <p>A highways inspector has now assessed the site you reported and arranged a non-urgent works instruction.</p> <p>17.09.2021 Reported again, as sign in danger of falling.</p> <p>Reported number 4202868 – reported by resident on 23.06.2021</p> <p>01.01.2022 reported again, as Chairman provided two photos.</p> <p>This is an update to your enquiry dated 01/01/2022 in relation to BENNETTS LANE.</p> <p>A highways inspector has now assessed the site you reported and arranged a non-urgent works instruction.</p>
Pot hole, on the hill going from Bramshall Industrial Estate towards Bramshall, postcode used ST14 5BG (Bank Farm)	19.05.2021	4242041		Clerk reported after a conversation with resident
Hollington Lane, Stramshall ST14 5AJ White Bollards to be added to existing ones (just past No 4)	17.09.2021	4255483	29.12.2021 Council to discuss 1 st February 2022 meeting. CLOSED	<p>Parish Council voted to add 4 bollards and repair 1 bollard – SCC gave permission</p>
Pavement tarmac damage, Olive Tree, High Street,	12.10.2021	4257847	04.11.2021	<p>Reported by resident at October 2021 meeting.</p> <p>SCC updated:</p> <p>This is an update to your enquiry dated</p>

STramshall ST14 5AL				12/10/2021 in relation to HIGH STREET. A highways inspector has now assessed the site you reported and arranged a non-urgent works instruction.
Trees obstructing visibility on Stafford Road, nearest postcode Loxley Hall School, ST14 8RS	22.10.2021	4258923		Reported by councillor in October 2021 meeting
Request for layby to be created on Hollington Lane, Stramshall, ST14 5AJ within grass verge outside No 3 & 4	24.11.2021	4261716	29.12.2021 CLOSED	This was requested by residents. photo included This is an update to your enquiry dated 24/11/2021 in relation to HOLLINGTON LANE . A highways officer has now considered your enquiry and added the following notes to your report: Due to on going cut backs there are no plans or funding to make changes at this location in the near future, sorry i can not be more helpful regarding this issue
Salt bin – requested by resident for Bramshall. Location verge on B5027/Church Lane Nearest Postcode ST14 5BG	08.12.2021	4263468	17.12.2021 01.02.2022 Closed	Resident requested, SCC advised to use Report it, so area can be accessed. If SCC says no, we can adopt a community salt bin. An assessment has been undertaken at this location and does not qualify under the winter maintenance policy for a grit bin, This area Church Lane junction of Stone Road Bramshall, Scores 60 out of the required 100 points when assessed against the winter service policy "WS7" form. Stone Road and Church Lane are both on gritting routes I am sorry that I cannot be more positive in my response. Parish Council will investigate Community Grit Bin -
Newton House, Stone Road, Bramshall, ST14 5BG	17.12.2021	4264350		Road surfacing took place, they surfaced too high, so rain running down driveway. Photos included

Road Sign – direction arm is broken - Junction of Church Lane and B5027 Nearest Postcode ST14 5BG	21.12.2021	4264631	04.01.2022	The direction arm on the Road side sign has broken. Photos x2 attached. This is an update to your enquiry dated 21/12/2021 in relation to STONE ROAD. A highways inspector has now assessed the site you reported and arranged a non-urgent works instruction.
Spath Layby – ST14 5AD Vegetation overgrown on the humps that block the old Uttoxeter Road	01.02.2022	4268595		Included photo of the overgrown vegetation in report.
Gully Blocked Opposite Entrance of The Walled Garden, St Michaels Road, Stramshall Uttoxeter ST14 5DU	08.02.2022	4269411		Resident reported this issue via private email address