## URPC Highways Reporting Log –2022

All issues were reported to Staffordshire County Council via the Report It function <a href="https://www.staffordshire.gov.uk/reportit">www.staffordshire.gov.uk/reportit</a>

## Salting and gritting map

## https://www.staffordshire.gov.uk/transport/staffshighways/winterdriving/salting/Saltingroutes.aspx

Demants 11	D-4-	I Carley	F-11-	0
Reported issue	Date	Highways	Follow up	Comments
- location and	reported	reference number	date	
requested		number		
action Pot hole and	21.10.2017	4094161	24.10.2017	Sent photo of large pot hole and flattened black and white posts.
	21.10.2017	4094101		Sent photo of large pot hole and nattened black and white posts.
flattened		4004004	01.03.2018	
black/white		4201024	23.05.2018	
posts on corner			01.11.2018	
of			20.02.2019	
A522/Waterloo			20.02.2013	
Farm,				637
Pigeonhay			10.06.2020	
Lane,				MINISTRA
			24.07.2020	04.44.2040 salad sallad historian farana undaka sa nakisad khis
Beamhurst,				01.11.2018 – clerk called highways for an update, as noticed this
ST14 5dy			19.01.2022	still not completed – scheduling team advised they will highlight it
			19.01.2022	20.02.2019 – this is with the scheduling team, as a CAT 3
				10.06.2020 Reported again, as main road has been repaired, but
				this is still on their system as awaiting scheduling team.
				24.07.2020
				This is an update to your enquiry dated 10/06/2020 in relation to
				PIGEONHAY LANE.
				THOUSAND BINE.
				A highways inspector has now assessed the site you reported and
				arranged a non-urgent works instruction.
				19.01.2022 – received an email from SCC to say this issue is on
				going.
				gonig.
The Cedars	28.01.2020	4186841		Resident reported it and provided photos
Hollington Lane				
STramshall				
ST14 5AJ				
guttering				
installed and				
water being				
discharged onto				
the road				
<u> </u>				
Flooding on	10.04.2020	4196935	22.04.2020	Map included of area, with arrow to culvert and map of drains in
Road, blocked				the area.
culvert under			06.05.2020	
road.				
		•	•	

Dairy Farm, High Street, Stramshall, ST14 5AG  Lamp post 23 Lamp post 22		Reported again 4198897  New Ref for 20.01.2021 report 4224656	15.05.2020 28.05.2020 20.07.2020 Closed Reopened 20.01.2021	This is an update to your enquiry dated 10/04/2020 in relation to HIGH STREET.  A highways officer has now considered your enquiry and added the following notes to your report: We have visited the location provided with your report but have been unable to identify any defects that require remedial works at this time. It might be that the problem has now been resolved. However; if you believe there is still an issue that requires attention may we kindly ask that you contact us again with your reference number so that we can verify the location details.  Sent to Councillors 22.04.2020  Trevor Mellor will carry out a site visit today 06.05.2020.  15.05.2020 – Site visit carried out, Landowner cleared mud from grid at entrance to pipe, Clerk reported again, providing lamp post 23 as a location.  28.05.2020  This is an update to your enquiry dated 15/05/2020 in relation to STRAMSHALL ROAD.  A highways inspector has now assessed the site you reported and arranged a non-urgent works instruction – jetting machine  20.07.2020  This is an update to your enquiry dated 15/05/2020 in relation to STRAMSHALL ROAD.  Works have taken place in response to your report. Other works in the area might still be pending and any unresolved defects will continue to be monitored via our routine safety inspections.  reopened 20.01.2021  Clerk took photos of the flood water on the road and reported the issue again. The landowner believes that Lamp post 23 has been installed through the drain land that is why it is going onto the road ont through the drain land what is why it is going onto the road ont through the drain land what is why it is going onto the road ont through the drain and that is why it is going onto the road ont through the drain and that is why it is going onto the road ont through the drain and that is why it is going onto the road ont through the drain and that is why it is going onto the road ont the road and reported the road ont through the drain and that why it is going onto the road onto the road onto the road onto
				the area might still be pending and any unresolved defects will continue to be monitored via our routine safety inspections.  reopened 20.01.2021  Clerk took photos of the flood water on the road and reported the issue again. The landowner believes that Lamp post 23 has been
Road sign	15.07.2020	4205119	17.07.2020	Cllr provided photo of broken sign
broken A50 – A518 junction  Nearest postcode ST14 5AA The McDonalds				Dear Mrs Uttoxeter Rural Parish Council. This is an update to your enquiry dated 15/07/2020 in relation to A518 ASHBOURNE ROAD.  A highways inspector has now assessed the site you reported and arranged a non-urgent works instruction.
Bramshall Village Sign not visible as overgrown hedge on verge	4216133	23.10.2020	23.04.2021	Checked for update on SCC Website – notes are: Your enquiry is currently allocated to a Highways officer and will be updated as soon as possible. We receive around 4000 highway related reports every month. But

		ı	1	1 11 12 12 12 12 12 12 12 12 12 12 12 12
on industrial				we have a limited number of officers to investigate and
estate side of				respond to these.
the village				
Nearest				
postcode Daisy				
Bank, Stone				
Road,				
Bramshall,				
ST14 8SH				
01110011				
Bennetts Lane,	4231297	23.02.2021	19.03.2021	This is an update to your enquiry dated 23/02/2021 in relation to
gullies blocked				BENNETTS LANE.
by mud				
				A highways officer has now considered your enquiry and added the
Bramshall ST14				following notes to your report:
5BN				
				Thank you for your enquiry work has already been raised for
				multiple gullies in this location and will be carried out as soon as
				scheduling and resources allow
0: 111 0:	4000015	45.64.5		
Give Way Sign	4238240	15.04.2021	27.04.2021	Two photos sent with report, the sign will fall into the road if not
– Damaged	4255484			repaired soon.
Bennetts	4233464			This is an update to your enquiry dated 15/04/2021 in relation to
Lane/Stone	4202868		17.09.2021	BENNETTS LANE.
Road, Bramshall			Reported	
ST14 5BG	4265245		again, new	A highways inspector has now assessed the site you reported and
3114300			number	arranged a non-urgent works instruction.
			issued	17.09.2021 Reported again, as sign in danger of falling.
			133000	
			01.01.2022	Reported number 4202868 – reported by resident on 23.06.2021
			Reported	01.01.2022 reported again, as Chairman provided two photos.
			again	
				This is an update to your enquiry dated 01/01/2022 in relation to
			04.01.2022	BENNETTS LANE.
				A highways inspector has now assessed the site you reported and
				A highways inspector has now assessed the site you reported and
				arranged a non-urgent works instruction.
Pavement	12.10.2021	4257847	04.11.2021	Reported by resident at October 2021 meeting.
tarmac				
damage, Olive			12.04.2022	SCC updated:
Tree, High				This is an update to your enquiry dated 12/10/2021 in relation to
Street,				HIGH STREET.
Stramshall				A highways inspector has now assessed the site you reported and
ST14 5AL				arranged a non-urgent works instruction.
				2
				We have not yet been able to coordinate resources to resolve the
				enquiry you raised, due to high demand for reactive maintenance
				work across our road network.
				We write to assure you that we have not forgotten about the issue
				and will endeavour to schedule the necessary works as soon as is
				practicably possible.

Trees	22.10.2021	4250022		Panartad by councillar in October 2021 masting
obstructing visibility on Stafford Road, nearest postcode Loxley Hall School, ST14 8RS	ZZ. IV.ZVZT	4258923		Reported by councillor in October 2021 meeting
Grit Salt bin – Salt Box requested by resident for Bramshall. Location verge on B5027/Church Lane Near The Croft driveway, Stone Road Nearest Postcode ST14 5BQ	08.12.2021	4263468  Community Grit Bin request 4275940	17.12.2021 01.02.2022 22.03.2022 14.06.2022	Resident requested, SCC advised to use Report it, so area can be accessed. If SCC says no, we can adopt a community salt bin.  An assessment has been undertaken at this location and does not qualify under the winter maintenance policy for a grit bin, This area Church Lane junction of Stone Road Bramshall, Scores 60 out of the required 100 points when assessed against the winter service policy "WS7" form.  Stone Road and Church Lane are both on gritting routes  I am sorry that I cannot be more positive in my response.  Parish Council will investigate Community Grit Bin  The Parish Council voted to request a community Grit Bin in meeting 01.03.2022  Sent photos to SCC of the location – it is just after The Croft driveway.
Road Sign – direction arm is broken - Junction of Church Lane and B5027  Nearest Postcode ST14 5BG  Gully Blocked	21.12.2021	4264631	04.01.2022	The direction arm on the Road side sign has broken. Photos x2 attached.  This is an update to your enquiry dated 21/12/2021 in relation to STONE ROAD.  A highways inspector has now assessed the site you reported and arranged a non-urgent works instruction.  Resident reported this issue via private email address
Opposite Entrance of The Walled Garden, St Michaels Road, Stramshall				

Uttoxeter ST14				
5DU				
Creighton Lane, Stramshall, ST14 5AF Flooding continues on cornor (Bridge Cottage end)	22.02.2022	4271697 4280335	08.03.2022 03.05.2022	Included two photos – one with drain covered in water and the other with no water, so can see comparison.  08.03.2022 – highways updated Current Status: No Further Highways Action  03.05.2022 – Reported again and asked if Landowner could be contacted, so water has somewhere to go – attached two photos, one o the flooding and one of the drain
Dairy Farm, High Street, Stramshall, ST14 5AG  Flooding on side of road – locally it has always been thought that Lamp Post M23 and M22 have been installed through drain, hence water leaves open ditch and travels down the side of road to the first open manhole cover	23.02.2022	4271842 4276225	08.03.2022 23. 03.2022	Reported with photos and map of drains in area.  This has been reported many times and SCC have put cameras down, but still no resolution.  08.03.2022 – update from Highways  We have visited the location provided with your report but have been unable to identify any defects that require remedial works at this time. No further Action  Reported again on 23.03.2022
30mph signs in Stramshall, from Poppits Lane all the way down high street to Broomyclose lane Nearest postcode ST14 5AL Alder Bank Filling Station	17.06.2022	4285323	09.08.2022	As you travel from Loxley to Stafford, the hedge/vegetation is on the right hand side and is blocking visibility on the corner.
postcode ST14 8RU Junction of A518/Watery Lane			CLOSED	The exact location is where the A518 has a junction with Watery Lane and the overgrown vegetation is opposite Watery Lane.  The junction has a history of fatalities and therefore the Parish Council consider this request to be urgent.

vegetation				09.08.2022 – SCC provided the following:
blocking				Logged On: 17/06/2022
visibility				Logged On. 17/00/2022
Violonity				Request Type: ARBS – Hedge Overgrown
				Location: STAFFORD ROAD, LOWER LOXLEY
				Current Status: Unable to Action
				The County Council carry out grass cutting on highway verges to improve visibility and road safety.
				In urban areas grass verges are generally cut six times a year.
				However, some of this work is enhanced by the local District /
				Borough Council.  The County Council is not In a position to carry out works to
				improve the aesthetics or tidiness of an area and as such grass
				cuttings are left to mulch down into the verge areas rather than be collected.
				The County Council carry out Rural grass-cutting broadly on roads
				with a speed limit of 40mph or above on to maintain visibility and
				to ensure the safety of highway users and there are various
				contractors engaged in this work on our behalf, around the county.
				In rural areas, our higher priority routes are cut three times each
				year to a width of 1 metre; lower priority routes are cut twice.
				Visibility splays at junctions and bends are generally cut to full
				width.  The problem you have reported has been inspected and as it is not
				currently posing a safety issue, the site will be treated according to
				the programme as above and will continue to be monitored during
				routine inspections.
Lowley Hall	17.06.2022	4285321	09.08.2022	As you travel from Loxley Lane/Bennetts Lane to join the A518
School		1200021	03.00.2022	(Stafford Road), the vegetation/hedges is blocking the visibility of
On 4510				road users and is causing a hazard.
On A518 Junction with			CLOSED	This junction is dangerous without the visibility issue and the Parish
Bennetts Lane ST14 8RS				Council consider this to be an urgent request.
				09.08.2022 SCC updated
				Logged On: 17/06/2022
				Request Type: ARBS – Hedge Overgrown
				Location: STAFFORD ROAD, LOXLEY
				Current Status: Unable to Action
				The County Council carry out grass cutting on highway verges to improve visibility and road safety.
				In urban areas grass verges are generally cut six times a year.
				However, some of this work is enhanced by the local District /
				Borough Council.
				The County Council is not In a position to carry out works to
				improve the aesthetics or tidiness of an area and as such grass

			T	
Narrow Road Sign, by Railway Crossing/Bridge	22.06.2022	4285778	24.06.2022	cuttings are left to mulch down into the verge areas rather than be collected.  The County Council carry out Rural grass-cutting broadly on roads with a speed limit of 40mph or above on to maintain visibility and to ensure the safety of highway users and there are various contractors engaged in this work on our behalf, around the county. In rural areas, our higher priority routes are cut three times each year to a width of 1 metre; lower priority routes are cut twice.  Visibility splays at junctions and bends are generally cut to full width.  The problem you have reported has been inspected and as it is not currently posing a safety issue, the site will be treated according to the programme as above and will continue to be monitored during routine inspections.  Cllr Jones provided two pictures that were submitted.  A highways officer has assessed the site you reported and arranged a non-urgent work instruction. The outcome of the assessment
on Bennetts Lane/Loxley Lane – pushed over and turning wrong way so no one can see it				means this defect does not pose an immediate risk to public safety.  Our priority is to be effective at responding to the most serious problems on the network, therefore we are unable to provide a delivery date for defects of a non-urgent nature, until such time that resources become available.
Spath Roundabout B5030 /A518 meet in Spath pine trees damaged and road signs	29.07.2022	4289581 Signs 4289585 tree damage	06.09.2022	Clerk reported to MJ Barretts and they requested reporting to SCC, as they only cut grass and significant damage to the trees has occurred.  Reported as two, the signage damage and the tree damage
damaged ST14 5AP		4293537 damaged trees reported again 13.09.2022		06.09.2022 SCC replied to 4289585 to say they could not find the tree on the roundabout, so reported it again, this time with photos on 13.09.2022
JCB Beamhurst – pot hole by	12.10.2022	4296031	14.10.2022	Add photo – JCB Beamhurst pot hole 2

bus stop near				
roundabout				
			Closed	SCC replied with the following:
Nearest				
postcode ST14				Thank you for your enquiry. We can confirm that work has been
5PA				
J A				raised for multiple defects in this area, which will be carried out as
				soon as scheduling and resources allow.
JCB Beamhurst	12.10.2022	4296033	14.10.2022	Added photo – JCB Beamhurst pot hole 1
– pot hole by				·
bus stop near				SCC replied with the following:
roundabout -				, , , , , , , , , , , , , , , , , , ,
opposite side of			closed	Thank you for your enquiry. We can confirm that work has been
				raised for multiple defects in this area, which will be carried out as
road to above				
Nearest				soon as scheduling and resources allow.
postcode				
ST14 5PA				
JCB Beamhurst	12.10.2022	4296035	14.10.2022	Added photo – JCB Beamhurst pot hole 5
<ul><li>deep pot hole</li></ul>				
on edge of				SCC replied with the following:
roundabout				
			closed	Thank you for your enquiry. We can confirm that work has been
Nearest				raised for multiple defects in this area, which will be carried out as
postcode ST14				soon as scheduling and resources allow.
5PA				
JCB Beamhurst	12.10.2022	4296038	14.10.2022	Added photo – JCB Beamhurst pot hole 4
<ul><li>deep pot</li></ul>				·
holes in centre			Closed	SCC replied with the following:
of road			2.5554	
oi ioau				Thank you for your enquiry. We can confirm that work has been
Nearest				
				raised for multiple defects in this area, which will be carried out as
postcode ST14				soon as scheduling and resources allow.
5PA				
0	40.40.0000			( and ( Processorates ) South Administry ( )
Screen shot of	12.10.2022		Closed,	1110
all reports of all			see above	
issues on JCB			SCC reply	Address of the second s
Beamhurst				The same of the sa
roundabout				The same of the sa
				0.0 0
				On O 10 110
Sent email to				
SCC Highways				The same and the s
Team for an				A CONTRACT OF THE PARTY OF THE
update				The state of the s
upuale				* / (account / 2011