0300 111 8000 <u>www.staffordshire.gov.uk/reportit</u> <u>highways@staffordshire.gov.uk</u>

## Salting and gritting map

## https://www.staffordshire.gov.uk/transport/staffshighways/winterdriving/salting/Saltingroutes.aspx

Deported issue	Doto	Highways	Follow:	Comments
Reported issue – location and	Date	Highways reference	Follow up date	Comments
requested action	reported	number	uale	
Speed hump –	06.09.2016	4057434	20.09.2016	This request could be included in the Stramshall S106
request a new one	00.03.2010	700170 <del>1</del>	28.02.2017	•
be installed on the				funding plan, Cllr Oulsnam to consider
			01.03.2017	
corner of St			01.11.2018	
Michaels Road,				
Cedar Drive and				
Hollington Lane,				
Stramshall				
0744.540				
ST14 5AQ				
Pot hole and	21.10.2017	4094161	24 10 2017	Cont what of large not halo and flattened black and
flattened	21.10.2017	4034101	24.10.2017	Sent photo of large pot hole and flattened black and
			01.03.2018	white posts.
black/white posts			23.05.2018	
on corner of			01.11.2018	
A522/Waterloo			20.02.2019	
Farm, Pigeonhay				
Lane, Beamhurst,				4. 图 10. 图 1
ST14 5dy				
				Minister
				THE PROPERTY OF THE PARTY OF TH
				01.11.2018 – clerk called highways for an update, as
				noticed this still not completed – scheduling team
				advised they will highlight it
				20.02.2019 – this is with the scheduling team, as a
				_
				CAT 3
Stramshall Road	12.03.2019	4151890	20.03.2019	Included abote growh
sign collapsed,	12.03.2019	4101090	29.01.2020	Included photograph
corner of A518				Street sign damage is ESBC not SCC, resent to ESBC
			CLOSED	Street sign damage is ESDC HOLSCO, resemble to ESDC
and Stramshall				Finallad and a factor of the state of
Road				Emailed again as for an as sign still not replaced,
ST14 5AF				collected April 2019 – replaced
3114 3AF				
Ct Michaela Deed	10.00.0010	4464450	20.14.2010	Culturalista of which many of the course Could be 1971
St Michaels Road,	12.06.2019	4161159	29.11.2019	Submitted with map of the area. Saved in highways
Stramshall				folder.
The demonstrate				This is an update to your enquiry dated 12/06/2019
The damage to				in relation to ST MICHAELS ROAD.
the road side				
verges is from				
Poppits				
lane,Stramshall				
where Trafalgar				

House is, postcode ST14 5AH, all the way from there, on the right side of the road (adjacent to the ditch), down to Springfields ST14 5AH. (on map Wheat M&SR). The edge of the road is eroded due to raining running down the road.				A highways inspector has now assessed the site you reported and arranged a non-urgent works instruction.
Cycle Path – The Doveway Flyover A518 Overgrown cycle path	09.07.2019	4164101	08.01.2020	3 photos sent with report plus map of area  The cycle path is on The Dove Way fly over A518  update from SCC below 08.01.2020  This is an update to your enquiry dated 09/07/2019 in relation to THE DOVE WAY.  A highways inspector has now assessed the site you reported and arranged a non-urgent works instruction.
Traffic Counting for Stramshall  Requested SCC do a traffic count for Stramshall	June 2019		09.07.2019	3 reports were provided by SCC, one of volume, one of speed, one of length of the vehicle. Sent to Councillors
Loxley Lane Crossing, Lower Loxely	29.09.2019			Crash at junction, resulting in a fatality, Kingstone PC, Marchington PC offered help to resolve the issue. Clerk provided Councillors with the details of work carried out in 2017 from the Highways Log.
National Speed Limit sign broken Willowbrook Farm Highwood Uttoxeter ST14 8NW	24.01.2020	4186278	29.01.2020	Dear Mrs Uttoxeter Rural Parish Council  This is an update to your enquiry dated 24/01/2020 in relation to HIGHWOOD ROAD.  A highways inspector has now assessed the site you reported and arranged a non-urgent works instruction.
The Cedars Hollington Lane STramshall	28.01.2020	4186841		Resident reported it and provided photos

ST14 5AJ  guttering installed and water being discharged onto the road				
Kerb Side of Speed hump has crumbled away, by - South View Spath ST14 5AF	31.01.2020	4187437 4187844	04.02.2020	Resident reported damage to car to Chairman.  A resident of Stramshall has damaged his tyre on a speed hump,  because the side edge of, the speed hump, it has crumbled away  Added photo provide by Cllr Moore to the original report.
Pot hole with tarmac missing from around metal grid– broomyclose lane/high street, Stramshall entrance	04.02.2020	4187839		Photos provided by Cllr Moore.
Pot holes by broomyclose lane and on high street, ST14 5AN	04.02.2020	4187842		Photos provided by Cllr Moore
Pot hole by Speed Hump, South View, Spath ST14 5AF	04.02.2020	4187843		Photo provided by Cllr Moore