


URPC Highways Reporting Log –2020 - 2021

All issues were reported to Staffordshire County Council via the Report It function

www.staffordshire.gov.uk/reportit

Salting and gritting map

<https://www.staffordshire.gov.uk/transport/staffshighways/winterdriving/salting/Saltingroutes.aspx>

Reported issue – location and requested action	Date reported	Highways reference number	Follow up date	Comments
Speed hump – request a new one be installed on the corner of St Michaels Road, Cedar Drive and Hollington Lane, Stramshall ST14 5AQ	06.09.2016	4057434	20.09.2016 28.02.2017 01.03.2017 01.11.2018 09.11.2019 19.03.2021	This request could be included in the Stramshall S106 funding plan, Cllr Oulsnam to consider included in site visit with SCC, but no plans to be issued until after April 2020. Plans for S106 will be with Parish Council by Summer 2021
Pot hole and flattened black/white posts on corner of A522/Waterloo Farm, Pigeonhay Lane, Beamhurst, ST14 5dy	21.10.2017	4094161 4201024	24.10.2017 01.03.2018 23.05.2018 01.11.2018 20.02.2019 10.06.2020 24.07.2020	Sent photo of large pot hole and flattened black and white posts.  01.11.2018 – clerk called highways for an update, as noticed this still not completed – scheduling team advised they will highlight it 20.02.2019 – this is with the scheduling team, as a CAT 3 10.06.2020 Reported again, as main road has been repaired, but this is still on their system as awaiting scheduling team. 24.07.2020 This is an update to your enquiry dated 10/06/2020 in relation to PIGEONHAY LANE. A highways inspector has now assessed the site you reported and arranged a non-urgent works instruction.
Cycle Path – The Doveway Flyover A518	09.07.2019	4164101	08.01.2020 10.02.2021	3 photos sent with report plus map of area The cycle path is on The Dove Way fly over A518 update from SCC below 08.01.2020

Overgrown cycle path			Closed	<p>This is an update to your enquiry dated 09/07/2019 in relation to THE DOVE WAY.</p> <p>A highways inspector has now assessed the site you reported and arranged a non-urgent works instruction.</p> <p>12.02.2021</p> <p>This is an update to your enquiry dated 09/07/2019 in relation to THE DOVE WAY</p> <p>Works have taken place in response to your report and no further tasks are planned at this time</p>
<p>The Cedars Hollington Lane STramshall</p> <p>ST14 5AJ</p> <p>guttering installed and water being discharged onto the road</p>	28.01.2020	4186841		Resident reported it and provided photos
<p>Pot hole with tarmac missing from around metal grid– broomyclose lane/high street, Stramshall entrance</p> <p>ST14 5AN</p>	04.02.2020	<p>4187839</p> <p>4201022</p>	<p>14.02.2020</p> <p>10.06.2020</p> <p>12.06.2020</p>	<p>Photos provided by Cllr Moore.</p> <p>Dear Mrs Uttoxeter Rural Parish Council This is an update to your enquiry dated 04/02/2020 in relation to HIGH STREET. A highways officer has now considered your enquiry and added the following notes to your report:</p> <p>Sunken fire hydrant cover is responsibility of ssw. They have been made aware of this report</p> <p>reported again with Cllr Moore photo</p> <p>12.06.2020- This is an update to your enquiry dated 10/06/2020 in relation to HIGH STREET.</p> <p>A highways inspector has now assessed the site you reported and arranged a non-urgent works instruction.</p>
<p>Bramshall Chicane</p> <p>Bollard knocked over</p> <p>ST14 5NE</p>	04.02.2020	<p>4187936</p> <p>4235518</p>	<p>14.02.2020</p> <p>23.03.201</p>	<p>Dear Uttoxeter Rural Parish Council</p> <p>This is an update to your enquiry dated 04/02/2020 in relation to STONE ROAD.</p>

				<p>A highways officer has now considered your enquiry and added the following notes to your report:</p> <p>Work has already been raised for this location and is now awaiting to be scheduled.</p> <p>Repair carried out and then bollard knock off again – reported again.</p>
<p>Drain collapse</p> <p>Hook Lane STramshall</p>	19.02.2020	4190390		<p>Resident reported this issue.</p> <p>There is a problem with drainage in that area and I note that whilst SCC tackle problems there issue by issue I do wonder if a 'bigger picture' needs to be taken as Hook Lane does turn to stream and is being destroyed maybe because the drain in question needs a major review.</p> <p>Thank you for your report dated 19/02/2020 in relation to the location of HOOK LANE. The event on the highway you have reported may require serious and immediate attention. It may be necessary for us to divert resources from other urgent and routine highway activities in order to assess/remedy the problem.</p>
<p>Blocked Drain</p> <p>Hollington Lane/St Michaels Road, by Church/Bus Stop</p> <p>ST14 5AH</p>	19.02.2020	4190398	03.2021	<p>Resident emailed clerk, clerk reported it.</p> <p>Sand is blocking drain and water running down the high street as a result.</p> <p>Awaiting works to fix the fault.</p>
<p>Springfield,</p> <p>St Michaels Road, Stramshall ST14 5DU</p> <p>Blocked gully, flooding as a result</p>	26.02.2020	4192044	03.2021	Awaiting site visit
<p>Flooding on Road, blocked culvert under road.</p> <p>Dairy Farm, High Street, Stramshall, ST14 5AG</p> <p>Lamp post 23 Lamp post 22</p>	10.04.2020	<p>4196935</p> <p>Reported again</p> <p>4198897</p>	<p>22.04.2020</p> <p>06.05.2020</p> <p>15.05.2020</p> <p>28.05.2020</p> <p>20.07.2020</p>	<p>Map included of area, with arrow to culvert and map of drains in the area.</p> <p>This is an update to your enquiry dated 10/04/2020 in relation to HIGH STREET.</p> <p>A highways officer has now considered your enquiry and added the following notes to your report: We have visited the location provided with your report but have been unable to identify any defects that require remedial works at this time. It might be that the problem has now been resolved. However; if you believe there is still an issue that requires attention may we kindly ask</p>

		<p>New Ref for 20.01.2021 report</p> <p>4224656</p>	<p>Closed</p> <p>Reopened 20.01.2021</p>	<p>that you contact us again with your reference number so that we can verify the location details.</p> <p>Sent to Councillors 22.04.2020</p> <p>Trevor Mellor will carry out a site visit today 06.05.2020.</p> <p>15.05.2020 - Site visit carried out, Landowner cleared mud from grid at entrance to pipe, Clerk reported again, providing lamp post 23 as a location.</p> <p>28.05.2020 This is an update to your enquiry dated 15/05/2020 in relation to STRAMSHALL ROAD.</p> <p>A highways inspector has now assessed the site you reported and arranged a non-urgent works instruction – jetting machine</p> <p>20.07.2020 This is an update to your enquiry dated 15/05/2020 in relation to STRAMSHALL ROAD .</p> <p>Works have taken place in response to your report. Other works in the area might still be pending and any unresolved defects will continue to be monitored via our routine safety inspections.</p> <p>reopened 20.01.2021 Clerk took photos of the flood water on the road and reported the issue again. The landowner believes that Lamp post 23 has been installed through the drain and that is why it is going onto the road, not through the drain. Included map of drains for the area with report.</p>
<p>Pot holes/ridges on main roundabout – nearest postcode is Staffordshire</p> <p>Traditional Meat, Spath Farm, ST14 5AP</p>	02.06.2020	4200322	<p>03.06.2020</p> <p>03.02.2021</p>	<p>B5030 and A518 roundabout</p> <p>This is an update to your enquiry dated 02/06/2020 in relation to ASHBOURNE ROAD.</p> <p>A highways inspector has now assessed the site you reported and arranged a non-urgent works instruction.</p> <p>Sent email to Cllr Brookes (SCC) asking if he could champion both this roundabout and Beamhurst one. Advised Highways will be informed.</p>

<p>Road sign broken A50 – A518 junction</p> <p>Nearest postcode ST14 5AA The McDonalds</p>	15.07.2020	4205119	17.07.2020	<p>Cllr Moore provided photo of broken sign</p> <p>Dear Mrs Uttoxeter Rural Parish Council. This is an update to your enquiry dated 15/07/2020 in relation to A518 ASHBOURNE ROAD.</p> <p>A highways inspector has now assessed the site you reported and arranged a non-urgent works instruction.</p>
<p>Bramshall Village Sign not visible as overgrown hedge on verge on industrial estate side of the village</p> <p>Nearest postcode Daisy Bank, Stone Road, ST14 8SH</p>	4216133	23.10.2020		
<p>Broomyclose Lane, towards Creighton Lane end. Nearest postcode is for Bridge Cottage, but this is on Creighton Lane.</p> <p>ST14 5AX</p> <p>The road is a single track that runs from the main Broomyclose Lane down towards Creighton Lane, Stramshall playing fields,</p> <p>The single track road has a number of pot holes and surface dressing has deteriorated.</p>	4216136	23.10.2020	25.11.2020	<p>This is an update to your enquiry dated 23/10/2020 in relation to BROOMYCLOSE LANE</p> <p>A highways officer has now considered your enquiry and added the following notes to your report:</p> <p>Thank you for your enquiry.</p> <p>All roads connected to Staffordshire's highway network are routinely inspected to identify safety defects. Any issues that are identified are raised for repair and categorised according to urgency.</p> <p>Work has already been raised for multiple defects at this location. If you wish to report a specific defect please contact us with a location and description of the defect that you are reporting</p> <p>If you have any queries on the response you have received, further information on how we respond to commonly reported highway issues, as well as frequently asked questions; are available on the 'Report It Explained' page under the Highways section of our website at www.staffordshire.gov.uk</p>
<p>Bennetts Lane, gullies blocked by mud</p> <p>Bramshall ST14 5BN</p>	4231297	23.02.2021	19.03.2021	<p>This is an update to your enquiry dated 23/02/2021 in relation to BENNETTS LANE.</p> <p>A highways officer has now considered your enquiry and added the following notes to your report:</p> <p>Thank you for your enquiry work has already been raised for multiple gullies in this location</p>

				and will be carried out as soon as scheduling and resources allow
Hill House Farm, St Michaels Road, Stramshall ST14 5AQ Tree Stump on verge, between Hill House Farm and Traffalgar House	4234945	19.03.2021		Included two photos – named Tree Stump in folder