

# URPC Highways Reporting Log –2019


0300 111 8000

[www.staffordshire.gov.uk/reportit](http://www.staffordshire.gov.uk/reportit)

[highways@staffordshire.gov.uk](mailto:highways@staffordshire.gov.uk)

## **Salting and gritting map**

<https://www.staffordshire.gov.uk/transport/staffshighways/winterdriving/salting/Saltingroutes.aspx>

Reported issue – location and requested action	Date reported	Highways reference number	Follow up date	Comments
Speed hump – request a new one be installed on the corner of St Michaels Road, Cedar Drive and Hollington Lane, Stramshall  ST14 5AQ	06.09.2016	4057434	20.09.2016 28.02.2017 01.03.2017 01.11.2018	This request could be included in the Stramshall S106 funding plan, Cllr Oulsnam to consider
Pot hole and flattened black/white posts on corner of A522/Waterloo Farm, Pigeonhay Lane, Beamhurst, ST14 5dy	21.10.2017	4094161	24.10.2017 01.03.2018 23.05.2018 01.11.2018 20.02.2019	Sent photo of large pot hole and flattened black and white posts.  01.11.2018 – clerk called highways for an update, as noticed this still not completed – scheduling team advised they will highlight it 20.02.2019 – this is with the scheduling team, as a CAT 3
Cllr Mark Deaville	19.09.2018			Sent an email to Cllr Deaville at SCC asking him to consider the request for traffic count on so that speeding cars on Abbots Bromley Road can be monitored. Also asked for an update on all issues on highways log that have been reported for over 60 days.
Stramshall Road sign collapsed, corner of A518 and Stramshall Road  ST14 5AF	12.03.2019	4151890	20.03.2019	Included photograph  Street sign damage is ESBC not SCC, resent to ESBC
St Michaels Road, Stramshall	12.06.2019	4161159	29.11.2019	Submitted with map of the area. Saved in highways folder.

The damage to the road side verges is from Poppits lane, Stramshall where Trafalgar House is, postcode ST14 5AH, all the way from there, on the right side of the road (adjacent to the ditch), down to Springfields ST14 5AH. (on map Wheat M&SR). The edge of the road is eroded due to raining running down the road.				<p>This is an update to your enquiry dated 12/06/2019 in relation to ST MICHAELS ROAD.</p> <p>A highways inspector has now assessed the site you reported and arranged a non-urgent works instruction.</p>
<p>Cycle Path – The Doveway Flyover A518</p> <p>Overgrown cycle path</p>	09.07.2019	4164101		<p>3 photos sent with report plus map of area</p> <p>The cycle path is on The Dove Way fly over A518</p>
<p>Traffic Counting for Stramshall</p> <p>Requested SCC do a traffic count for Stramshall</p>	June 2019		09.07.2019	3 reports were provided by SCC, one of volume, one of speed, one of length of the vehicle. Sent to Councillors
<p>Rocking manhole cover,</p> <p>Hollington Lane, high street, st Michaels road, stramshall</p> <p>Used St Michaels and All Angels Church postcode ST14 5AH</p>	12.07.2019	4164485	29.11.2019 CLOSED	<p>Attached a photo of the manhole cover</p> <p>SCC confirmed this had been resolved.</p>
<p>Traffic Lights at McDonalds not working ST14 5AA</p>	<p>01.08.2019</p> <p>06.08.2019</p>	<p>19275726 SCC 1597/6aug2019</p> <p>Highways England</p>	<p>06.08.2019</p> <p>Closed</p>	<p>Reported by residents and Chair to SCC</p> <p>Reported to Highways England</p> <p>Clerk had confirmation that SCC have reported to Highways England and resolution 06.08.2019</p>
Loxley Lane Crossing, Lower Loxely	29.09.2019			Crash at junction, resulting in a fatality, Kingstone PC, Marchington PC offered help to resolve the issue.

				Clerk provided Councillors with the details of work carried out in 2017 from the Highways Log.
Traffic Lights at McDonalds  ST14 5AA	08.10.2019		05.12.2019	Clerk asked for a sticker to be put onto the column of the lights, so residents can report faults.  Balfour Beatty confirmed signs are now on the traffic lights for residents to report any issues directly.