

# URPC Highways Reporting Log –2019


0300 111 8000

[www.staffordshire.gov.uk/reportit](http://www.staffordshire.gov.uk/reportit)

[highways@staffordshire.gov.uk](mailto:highways@staffordshire.gov.uk)

## **Salting and gritting map**

<https://www.staffordshire.gov.uk/transport/staffshighways/winterdriving/salting/Saltingroutes.aspx>

Reported issue – location and requested action	Date reported	Highways reference number	Follow up date	Comments
5 – 7 Pot holes Stocks Lane Junction of stocks lane and Stone Lane ST14 5NE	05.04.2016	4043109 4043863 4139163	05.04.2016 12.04.2016 24.06.2016 10.08.2016 20.09.2016 28.02.2017 14.04.2017 22.08.2017 13.09.2017 03.11.2017 02.07.2018 16.10.2018 19.10.2018 20.02.2019	Clerk took 2 more photos of potholes 16.10.2018 and submitted them again to highways and sent email to Cllr Deaville, SCC, copied Chair and Vice Chair into email.  19.10.2018 - This is an update to your enquiry dated 16/10/2018 in relation to STOCKS LANE. A highways inspector has now assessed the site and arranged for repairs to be carried out. The reported issue is not considered to be a high risk to public safety and so the repairs will be grouped with similar works in the area in order to be as efficient and cost effective as possible. Currently over 50% of these repairs take place within 60 days. The remaining defects are repaired as soon as resources are available. Traffic lights required for repair, hence the delay. This is a CAT 3 and it is with the schedulers. Only have limited resources at present.
Speed hump – request a new one be installed on the corner of St Michaels Road, Cedar Drive and Hollington Lane, Stramshall  ST14 5AQ	06.09.2016	4057434	20.09.2016 28.02.2017 01.03.2017 01.11.2018	This request could be included in the Stramshall S106 funding plan, Cllr Oulsnam to consider
Pot hole and flattened black/white posts on corner of A522/Waterloo Farm, Pigeonhay Lane, Beamhurst, ST14 5dy	21.10.2017	4094161	24.10.2017 01.03.2018 23.05.2018 01.11.2018 20.02.2019	Sent photo of large pot hole and flattened black and white posts.  01.11.2018 – clerk called highways for an update, as noticed this still not completed – scheduling team advised they will highlight it 20.02.2019 – this is with the scheduling team, as a CAT 3

17 pot holes from 32 Broomyclose lane ST14 5AN down FARM LANE towards the playing fields ST14 5AX	21.10.2017	4094165	24.10.2017 01.03.2018 01.11.2018 20.02.2019	01.11.2018 - Clerk contacted highways, scheduling team will be highlighted it. 20.02.2019 This is a CAT 3 and will be done when resources are available.
Gullies by Springfield Hse, Stramshall, ST14 5DU blocked	18.09.2018	4136376	24.01.2019 13.02.2019	Clerk requested that it be put on the regular maintenance report on Highways. This is an update to your enquiry dated 18/09/2018 in relation to ST MICHAELS ROAD . A highways inspector has now visited the site and added the following notes to the report:  These gulleys will be cleaned and plotted onto our system add hoc gulley machine when its in the area no dates can be given for this work 13.02.2019 All Gullies cleared out w/c 4.02.2019
B5030 - Quarry  Road Sign Blocked with Trees.  Location - Coming from Rocester on the B5030, it's the large information board on the approach to the roundabout which show roads for Uttoxeter Stafford A518 , or ahead for Stoke ,Derby A50 ,M6 North.  The land is the house near to it is Spath Cottage its opposite Staffordshire Traditional Meats  ST14 5AP	28.02.2017	4076870  4136473	28.03.2017 02.05.2017 14.09.2018 19.09.2018 02.10.2018 20.02.2019	Clerk requested highways to clear verge, advised it is land owner, which is Aggregate Industries. Aggregate Industries advised it is Highways, Highways have written to land owner Submitted a new request for trees to be cut to highways This is an update to your enquiry dated 19/09/2018 in relation to ASHBOURNE ROAD. A highways inspector has now visited the site and added the following notes to the report: Letter sent out in post to landowner 01.10.2018 JK Clerk sent an email to Aggregate Industries including the comments from Highways. Aggregate Industries visited site and advised all overgrown bushes are on highways land. 20.02.2019 – SCC have advised this is closed, as inspector has said not highways and to contact <a href="mailto:road.adoptions@staffordshire.gov.uk">road.adoptions@staffordshire.gov.uk</a> . To find out who owns this land.
Cllr Mark Deaville	19.09.2018			Sent an email to Cllr Deaville at SCC asking him to consider the request for traffic count on so that speeding cars on Abbots Bromley Road can be monitored. Also asked for an update on all issues on highways log that have been reported for over 60 days.
Flower Pots on Highways pavement, Old Smithy, Stone	28.09.2018	4137634	16.10.2018	Sent highways photos of the flower pots on the highway pavement and asked to investigate.

Road, Bramshall, ST14 5BG				<p>This is an update to your enquiry dated 28/09/2018 in relation to STONE ROAD.</p> <p>A highways inspector has now visited the site and added the following notes to the report:</p> <p>The issue you have reported is not within the public highway and we believe the area to be privately owned. Therefore, the County Council is not in a position to investigate the issue you have raised. However, should you wish to pursue this matter, you can contact Land Registry to identify the landowner using the following website:  <a href="https://www.gov.uk/government/organisations/land-registry">https://www.gov.uk/government/organisations/land-registry</a></p>
Robin Hood Signs – Brown – still in place throughout Bramshall Village  ST14 5NE  ST14 5DN	06.02.2019	4148275  4148279	13.02.2019	All Brown Signs removed
Brambles on verge – Stone Road, Bramshall  ST14 8TD  From village towards industrial unit.	20.02.2019	4149862		